

TERASIC PARTS REPLACEMENT DISCLAIMER

October 08, 2013

SUBJECT:

Engineering change notice for the USB controller chip ISP1362 on DE2-115 development board.

REASONS:

The supply of the original USB controller chip ISP1362 had reached EOL, so we've replaced it with Cypress CY7C67200.

IMPACT:


1. User manual/schematic will be updated.
2. USB source code included in the CD-ROM will be updated accordingly.
3. Existing software design will be changed in accordance to the feature/function of the new Cypress USB chip.
4. Hardware design will be changed due to the chip replacement.

COMPONENT REPLACEMENT TABLE:

AFFECTED PRODUCTS	EOL MEMORY MODULE	REPLACING MEMORY MOUDULE
Altera DE2-115 Development Board	USB controller chip ISP1362 (Terasic parts#: MIC3077-PLP)	Cypress CY7C67200-48BXI) (Terasic parts#: MIC-3513-CYP)

Thank you for your support of Terasic!

For any further question in regards of this ECN, please contact us at
<mailto:sales@terasic.com>



Sean Peng, CEO
Terasic Technologies